19990701.ba v02_n595.bam.990701

>From ???@??? Thu Jul 01 04:47:22 1999
Message-Id: <199907010501.d6151D002843@sco.theporch.com>
Date: Thu, 1 Jul 1999 00:00:04 CDT
From: Old Tube Radios <boatanchors@theporch.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: BOATANCHORS digest 2595

BOATANCHORS Digest 2595

Topics covered in this issue include:

1) Flexowriter manual
   by ail0@lehigh.edu (ARTHUR I. LARKY)
2) Moving sale.
   by Michael M Oxenreider <wb3ctc@juno.com>
3) Re: Moving sale.
   by Michael M Oxenreider <wb3ctc@juno.com>
4) 75A2 circular dial
   by john <johnmb@mindspring.com>
5) RE: Re RCA tube
   by "David Newkirk" <dpnewkirk@home.com>
6) NC-190 HELP
   by John M Iverson <jackiv@juno.com>

Message-Id: <199906302121.RAA39502@ns5-1.CC.Lehigh.EDU>
Date: Wed, 30 Jun 1999 17:20:45 EDT
From: ail0@lehigh.edu (ARTHUR I. LARKY)
Subject: Flexowriter manual
To: Old Tube Radios <boatanchors@theporch.com>

It took two hours in the basement, but I found the Flexowriter/Justowriter manual. It's 140 or so 2-sided pages and will cost between $10 and $15 to get copied depending upon the exact page count. (Postage for 2 or 3 pounds also required.) Anyone else interested? There is no quantity discount for having more copies made, but it would be convenient for me to have them all made at the same time. Let me know if you are interested.
Art K3HBA

To: Old Tube Radios <boatanchors@theporch.com>
Date: Wed, 30 Jun 1999 17:39:00 -0400
Subject: Moving sale.
Message-ID: <19990630.173902.-242357.0.WB3CTC@juno.com>
MIME-Version: 1.0
Content-Type: text/plain

Content-Transfer-Encoding: 7bit
From: Michael M Oxenreider <wb3ctc@juno.com>

Hello,
  Here are some heavy receivers that I don't want to move again.
These are pick up only in Lancaster county PA. South east part of the
state.
TMC GPR-90 w/ matching speaker and manual. $400
Espey R-366 /TRR-5 w/manual. $300
RCA CR-88
       $200
R-390A EAC 1967 Needs filter cap $200
All of them work and are in good condx.
73
Mike WB3CTC

To: Old Tube Radios <boatanchors@theporch.com>
Cc: boatanchors@theporch.com
Date: Wed, 30 Jun 1999 18:23:58 -0400
Subject: Re: Moving sale.
Message-ID: <19990630.182359.-242357.1.WB3CTC@juno.com>
MIME-Version: 1.0
Content-Type: text/plain
Content-Transfer-Encoding: 7bit
From: Michael M Oxenreider <wb3ctc@juno.com>

R-390a is sold

On Wed, 30 Jun 1999 17:39:00 -0400 Michael M Oxenreider <wb3ctc@juno.com>
writes:
>Hello,
> Here are some heavy receivers that I don't want to move again.
>These are pick up only in Lancaster county PA. South east part of the
>state.
>TMC GPR-90 w/ matching speaker and manual. $400
>Espey R-366 /TRR-5 w/manual. $300
>RCA CR-88
> $200
>R-390A EAC 1967 Needs filter cap $200
>All of them work and are in good condx.
>73
>Mike WB3CTC
>

Message-Id: <3.0.3.32.19990630193436.00ba73dc@mindspring.com>
Date: Wed, 30 Jun 1999 19:34:36 -0400

To: Old Tube Radios <boatanchors@theporch.com>
From: john <johnmb@mindspring.com>
Subject: 75A2 circular dial
Mime-Version: 1.0
Content-Type: text/plain; charset="us-ascii"

Folks,
My -A2 has for years been sullied by a scorched circular dial caused by the use of a non-standard pilot lamp set too close to the dial. Im getting ready to mate a Central Electronics Signal Slicer to my A2 for some Vintage SSB and would like to finally spiff up the appearance of the A2 to match the CE20/VFO and Slicer combo.

Does anyone know whether there's any repro circular dials made for this radio? If so, has anyone made the swap? I suppose removing the front panel is required for this swap, if there's one available.

Thanks very much!
/John

+---
| John Brewer- WB5OAU/4
| AMI #24   Vintage Radio Website
| http://www.mindspring.com/~johnmb/
+---

From: "David Newkirk" <dpnewkirk@home.com>
To: Old Tube Radios <boatanchors@theporch.com>
Subject: RE: Re RCA tube
Date: Wed, 30 Jun 1999 22:03:06 -0400
Message-ID: <000101bec365$dc486dc0$11670518@cc328679-a.vron1.nj.home.com>
MIME-Version: 1.0
Content-Type: text/plain;
     charset="iso-8859-1"
Content-Transfer-Encoding: 7bit

Phil McCoy wrote:

> The 6AC7 makes a poor RF amp or mixer. It is a low noise tube, but has
> a very low input impedance.

The 6AC7 makes a quite good RF amp or mixer at the appropriate frequency in a circuit of appropriate design. That its higher transconductance comes with increased input capacitance does tend to work against those ill-founded "just plug this hotter tube into Radio X and it'll work better" hopes, though. :-D

73,

Dave Newkirk, W9VES
dpnewkirk@home.com

To: Old Tube Radios <boatanchors@theporch.com>
Date: Tue, 29 Jun 1999 23:40:24 -0500
Subject: NC-190 HELP
Message-ID: <19990629.234027.13934.2.jackiv@juno.com>
From: John M Iverson <jackiv@juno.com>

I need real bad, a band switch knob for a NC-190 which I am trying to restore.
someone changed out the knob with one having o-10 in the 270 degree scale.
 This radio has suffered much mishandling in its life. The dial and bandspread mechanical drives are destroyed.
to repair I need a junker -190 or a -125. I belive that both these rx have the same friction dial drive components. Other than that it has a very god panel,cabinet and bottom plate. help, will buy or trade for this stuff. tnx   73 jack
Jack Iverson   K0EWU   jackiv@juno.com
ARRL, IEEE LM, RCA, AMI, ARCI, QCWA,CCA

_____
Get the Internet just the way you want it.
Free software, free e-mail, and free Internet access for a month!
Try Juno Web: http://dl.www.juno.com/dynoget/tagj.

End of BOATANCHORS Digest 2595
****